

Federal law prohibits removal of this label before consumer purchase.

Pioneer
Model YN018GLSI20RPF

A horizontal scale representing efficiency. The left end is marked with a vertical line and labeled '14.3' and 'Least Efficient'. The right end is marked with a vertical line and labeled '42.0' and 'Most Efficient'. Three tick marks are present on the scale at 14.3, 21.4, and 28.7. A black triangle points down to the 21.4 mark, which is labeled 'Average'.

 This system's efficiency ratings depend on the coil your contractor installs with this unit. The heating efficiency rating varies slightly in different geographic regions. Ask your contractor for details.

7.5 Least Efficient 14.6 Most Efficient

10.5

For energy cost info, visit
productinfo.energy.gov